


M 1:25



2.etapa



$\varnothing 12$; $L=1500\text{mm}$; 35ks
 $\varnothing 12$; $L=2370\text{mm}$; 20ks
 $\varnothing 12$; $L=1200+X$ mm; 12ks
 $\varnothing 12$; $L=1250\text{mm}$; 35ks
 $\varnothing 20$; $L=1000\text{mm}$; 5ks

