



PŘEHLEDNÁ SITUACE

An aerial photograph of a road intersection in a rural, forested area. A red rectangle is placed on the road, marking a specific location. A blue line follows the curve of the road, and a green line runs diagonally across the image. The surrounding area is mostly forested, with some buildings and a small clearing visible.

				Číslo soupavy:
Změna č.	Text změny – odůvodnění	Datum	Podpis	

Vypracoval: ING.JIŘÍ OBOZENKO	Zodp. projektant: ING.JIŘÍ OBOZENKO	HIP: ING.LUDĚK OBERHOFNER	Techn. kontrola: ING.JAN PROCHÁZKA
podpis:	podpis:	podpis:	podpis:
Obec: KARLOVY VARY	Kraj: KARLOVARSKÝ		
Objednatel: SPRÁVA ŽELEZNIČNÍ DOPRAVNÍ CESTY s.o., Dílčďdďnď 1003/7, 11000 Praha 1			
Zakázka: REKONSTRUKCE MOSTU V KM 48,927 TRATI MARIÁNSKÉ LÁZNĚ - KARLOVY VARY			
Nězev přilozy: PŘEHLEDNÁ SITUACE			
Zhotovitel:  PONTIKA s.r.o. IČO 26342669 Sportovní 4 360 09 Karlovy Vary tel. 353 228 240 pontika@pontika.cz			
Č. zakázky:		2016—66	
Datum:		4/2017	
Formát:		3A4	
Měřítiko:			
Stupeň PD:		PROJEKT	
Část:		Číslo přílohy:	
C1			