





26.6.2017

Počet listů: 5

Zakázkové číslo: 17-025-40-211		Jméno Tůma	Podpis 	 Pracoviště 211 – Ostrava	
Datum: 6.2017	Navrhl Kreslil	Tůma			
Stupeň dokumentace: DPSŘ	Kontroloval	Tůma			
Oprava PZS v km 39,022; 39,319; 39,577; 40,320; 40,885 a 41,692 trati Choceň – Týniště n. O. – Velký Osek PS01 PZS v km 39,022					1100
Průběh kabelových žil					

[illegible]

[illegible]

Výkr.	RD PZS 5H	K.č. 602	Spol.př.skříň										
číslo	stojan	7p1	SMO										
8004	042101	1	01										
8004	02	2	02										
8004	03	3	03										
8004	04	4	04										
8004	05	5	05										
8004	06	6	06										
8004	07	7	07										
8004	08	8	08										
8004	09	9	09										
8004	10	10	10										
8004	11	11	11										
8004	12	12	12										
	rez	13,14	rez										
	I	K.č. 603	Spol.př.skříň					K.č. 801	Výpich DK				
	I	3XN0,8	svorkovnice LSA					5XN0,8	děl. spojka				
	042201	1a	02-1a		VTOa	01-1a	1a	doplnit na stavbě					
	02	1b	1b		VTOb	1b	1b						
	03	1c	2a			2a	1c						
	04	1d	2b			2b	1d						
	05	2a	3a			3a	2a						
	06	2b	3b			3b	2b						
	07	2c	4a			4a	2c						
	08	2d	4b			4b	2d						
	09	3a	5a			5a	3a						
	10	3b	5b			5b	3b						
	11	3c	6a			6a	3c						
	12	3d	6b			6b	3d						
						7a	4a						
						7b	4b						
						8a	4c						
						8b	4d						
						9a	5a						
						9b	5b						
						10a	5c						
	RD PZS 5H					10b	5d						
	Skříňka	K.č. 601	Spol.př.skříň										
	na stěně	CYKY-O 2x1,5	VTO										
9900	2	1	+	VTO+									
9900	4	2	-	VTO-									

3.7.2017

Oprava PZS v km 39,022; 39,319; 39,577; 40,320 a 41,692 trati Choceň - Týniště n.O. - V. Osek

PS01 PZS v km 39,022

Průběh kabelových žil