






4.4.2017

Počet listů: 3

Zakázkové číslo: 17-025-40-211		Jméno Tůma	Podpis 	 Pracoviště 211 – Ostrava	
Datum: 6.2017	Navrhl	Tůma			
Stupeň dokumentace: DPSŘ	Kreslil	Tůma			
	Kontroloval	Tůma			
Oprava PZS v km 39,022; 39,319; 39,577; 40,320; 40,885 a 41,692 trati Choceň – Týniště n. O. – Velký Osek PS04 PZS v km 40,320					2600
Obsazení kontaktů relé					

NÁZEV	TYP	POZICE	DOTEKY A VINUTÍ JSOU NA VÝKRESE								
			VINUTÍ	1	2	3	4	5	6	7	8
AJ	NMŠM1-1500	08 01	8002	8002	8002	8003	8004	8007		8002	9001
AS	NMŠM1-1500	02	8002	8002	8002	8003	8002	8007			
BJ	NMŠM1-1500	03	8002	8002	8002	8003	8004	8007	8007	8002	9001
BS	NMŠM1-1500	04	8002	8002	8002	8003	8002	8007	8008		
X	NMŠ1-2000	05	8002			8002	8002	8007	8008		8001
D	NMŠ1-2000	06	8002	8002	8002	8003	8002	8007	8008		9001
DI	NMŠ1-2000	07	8002		8009		8009				
PDK	NMŠ1-2000	08	8004		8004	8003	8004	8007	8009	8009	9001
			VINUTÍ	1	2	3	4	5	6	7	8
1HJJ	NMŠ1-2000	07 01	7004					7001	7001	7001	7001
3HJJ	NMŠ1-2000	02	7004		8002			7001	7001	7001	7001
5HJJ	NMŠ1-2000	03	7004		8002			7001	7001	7001	7001
7HJJ	NMŠ1-2000	04	7004		8002			7001	7001	7001	7001
9HJJ	NMŠ1-2000	05	7004		8002		8004	7001	7001	7001	7001
HPB1SS	NMŠ1-2000	06	7004		8002		8007		8002		
HPB2LS	NMŠ1-2000	07	7004		8002		8007		8002		
PV	NMŠ1-2000	08	8004		8004				8008		
			VINUTÍ	1	2	3	4	5	6	7	8
UZ	NMŠ1-2000	06 01	8013	8001	8009	8009	8012	8012	8012		9001
OZ	NMŠ1-2000	02	8013	8003	8007	8002	8008	8013			9001
KUZ	NMŠ1-2000	03	8008	8007			8012	8012	8012		
KZP1	NMŠ1-2000	04	8012	8012	8009	8009	8012				9001
KZPP	NMŠ1-2000	05	8012	8012				8012			
TP	NMŠ1-2000	06	8008	8007	8013	8014	8012	8012			9001
NV	NMŠM1-1500	07	8008	8008	8009	8009			8007	8012	9001
SRQS	NMŠ1-2000	08	8003	8013	8014	8013	8014				
			VINUTÍ	1	2	3	4	5	6	7	8

4.4.2017

Oprava PZS v km 39,022; 39,319; 39,577; 40,320; 40,885 a 41,692 trati	2602
Choceň - Týniště n. O. - Velký Osek	
PS04 PZS v km 40,320	
Stojan 11: Obsazení kontaktů relé, patro 06-08	

