






30.6.2017

Počet listů: 1

Zakázkové číslo: 17-025-40-211		Jméno Tůma	Podpis 	 Pracoviště 211 – Ostrava
Datum: 6.2017	Navrhl	Tůma		
Stupeň dokumentace: DPSŘ	Kreslil	Tůma		
	Kontroloval	Tůma		
Oprava PZS v km 39,022; 39,319; 39,577; 40,320; 40,885 a 41,692 trati Choceň – Týniště n. O. – Velký Osek PS05 PZS v km 40,885				2600
Obsazení kontaktů relé				

NÁZEV	TYP	POZICE	DOTEKY A VINUTÍ JSOU NA VÝKRESE								
			VINUTÍ	1	2	3	4	5	6	7	8
DISTA		16 01	9001-02								
		02									
		03									
		04									
		05									
		06									
		07									
		08									
			VINUTÍ	1	2	3	4	5	6	7	8
DISTA		15 01	9001-02								
		02									
		03									
		04									
PR	NMŠ1-2000	05	8001	8009	8004	8009	8009	8009	8001	8001	9001
POST	NMŠ1-2000	06	8001		8007						9001
POSS	NMŠ1-2000	07	8001		8007		8004				9001
		08									
			VINUTÍ	1	2	3	4	5	6	7	8
DISTA		14 01	9001-02								
		02									
		03									
		04									
SRP	NMŠ1-2000	05	8007		8007		8007				
NSV	NMŠM1-1500	06	8007		8007		8007				9001
		07									
		08									
			VINUTÍ	1	2	3	4	5	6	7	8
SR	NMŠM1-1500	13 01	8003	8003	8006		8003		8007	8007	9001
SP	NMŠ1-2000	02	8004	8004	8005	8005	8004	8007			9001
SO	NMŠ2-4000	03	8005		8005		8005		8005		9001
		04									
OSRQ1	NMŠ1-2000	05	8003	8010	8005	8010	8005	8007	8004	8007	8009
OSRQ2	NMŠ1-2000	06	8003					8007			8009
SPQ1	NMŠ1-2000	07	8004	8005	8010	8005	8011		8007	8007	
SOQ1	NMŠ1-2000	08	8005	8005	8005					8007	8004
			VINUTÍ	1	2	3	4	5	6	7	8
NSKZ	NMŠ1-2000	12 01	8007	8007	8007	8001	8009	8009	8007		9001
KZ	NMŠM1-1500	02	8007	8007		8004	8009	8009			9001
NS	NMŠ1-2000	03	8007	8007			8009	8009			9001
TO	NMŠ1-2000	04	8004	8003		8007	8009	8009			9001
TZ	NMŠM1-1500	05	8004	8003		8007					9001
TON	NMŠ1-2000	06	8004	8004	8004						
DRBQ	NMŠ1-2000	07	8001	8001	8004		8009	8009	8004		9001
DRB	71 972e	08	8001								
			VINUTÍ	1	2	3	4	5	6	7	8
			VINUTÍ	1	2	3	4	5	6	7	8